600- 606 West Lexington Street

608- 616 West Lexington Street

Partial bearing wall failure at interior stairs of 602.

Northern structure at 600 with collapsed roof; structure appears to be rotating away from main building.

Collapse of 604's north roof.

Partial collapse of floor decking in 604.

Partial collapse of 610's wooden superstructure.

Partial floor collapse at north side of 612.

Detached masonry wall at 612.

Failure of third-story masonry structure at 614.

Partial collapse of 616's first floor and roof structure.